


# REPORT

## TRUESDAIL LABORATORIES, INC.



CHEMISTS - MICROBIOLOGISTS - ENGINEERS  
RESEARCH - DEVELOPMENT - TESTING

14201 FRANKLIN AVENUE  
TUSTIN, CALIFORNIA 92680  
AREA CODE 714 • 730-6239  
AREA CODE 213 • 225-1564  
CABLE: TRUE LABS  
January 29, 1990

CLIENT Douglas Aircraft Company  
Internal Mail Code 211-40  
3855 Lakewood Blvd.  
Long Beach, California 90846  
SAMPLE Attention: Kathleen Farretta M/C 211-46  
Monthly Storm Drain Inspection (December, 1989)  
P.O. No.: #T & M 23465 C

DATE  
RECEIVED December 22, 1989  
LABORATORY NO. 35540

### INVESTIGATION

Analysis as requested by the CRWQCB for NPDES Permit No.'s:  
CA0001486 & CA0001414

### RESULTS

A representative of Truesdail Laboratories, Inc. tested the storm drain discharge on December 22, 1989, at the Douglas, Long Beach (003) and Torrance facilities. The discharge was tested for flow rate, pH and temperature. The results are as follows:

<u>Sample I.D.</u>	<u>Date</u>	<u>Time</u>	<u>Flow-gpd</u>	<u>Temp</u>	<u>pH</u>
Long Beach (003)	12-22-89	10:21	45,593	60	8.0
Torrance	12-22-89	11:30	47	60	6.3

Respectfully submitted,  
TRUESDAIL LABORATORIES, INC.

Luis Perez, Supervisor  
Industrial Waste

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.